



NOTES:

1. LANDING SHALL NOT EXCEED 2% IN ANY DIRECTION.
2. TRUNCATED DOME DETECTABLE WARNING PANEL SHALL BE YELLOW POLYMER COMPOSITE/FIBERGLASS.
3. MID-BLOCK CROSSINGS SHALL USE THE SAME RAMP CONFIGURATION, EXCEPT THAT THERE WOULD BE A DIFFERENT RADIUS CURVE OR NO CURVE AT ALL.