



VACUUMS: There is a \$10.70 inspection fee due at the time your vacuum is checked in. If the repair total is over \$70.00 our technician will call you with an estimate before completing the repair work. If you choose not to have your unit repaired the inspection fee of \$10.70 is nonrefundable. If you choose to go ahead with the repair the inspection fee of \$10.70 is credited to the final cost of your repair bill.

Kirby, Filter Queen, Rainbows, Electrolux, Sharks and Dyson units will receive an estimate call if the repair total is over \$100.00.

Hoover Steam Vac units will receive an estimate call if the repair total is over \$85.00.

WE DO NOT REPAIR ANY OTHER BRANDS OF STEAM VAC MACHINES.

Vacuum Labor starting fees as follows:

- Bench Labor - \$18.50
- Simplicity Bypass Basic Tune-Up - \$29.50
- Simplicity Tandem Air Basic Tune - Up - \$38.50
- Simplicity Canister Labor - \$38.50
- XXX Brand Basic Tune-Up - \$28.50
- Bagless Unit Tune-Up/Repair - \$32.50
- Dyson/Shark Unit Tune-Up/Repair - \$42.50
- Kirby/ Filter Queen/ TriStar/ Compact/ Electrolux Unit Tune-Up/Repair - \$49.50
- Rainbow Tune-Up/Repair - \$109.50
- Hoover Steamvac/Shampooer Unit Tune-Up/Repair - \$48.50
- Power Nozzle Only Tune-Up/Repair - \$23.50

SEWING MACHINES, SERGERS, LONG-ARMS, ETC: There is a \$26.75 inspection fee due at the time your machine is checked in. If the repair total is over \$125.00 our technician will call you with an estimate before completing the repair work. If you choose not to have your unit repaired the inspection fee of \$26.75 is nonrefundable. If you choose to go ahead with the repair the inspection fee of \$26.75 is credited to the final cost of your repair bill.

Sewing Machine Labor starting fees as follows:

- Manual Machines - \$78.95-98.95
- Electronic Machines - \$99.95-109.95
- Computerized Machines with Embroidery Unit Service - \$129.95-149.95
- Sergers - \$99.95-\$109.95
- Longarm Quilting Machines - \$149.95
- Multi-Needle Embroidery Machines - \$149.95